



如是97#错误(齿轮模式溢出), 则清4B.1H, 否则往下走

清4B.1H GEAR ANDB 04BH, #0FDH

caused when the variable GEARI is too small or GEARO is too large. That is, the input times the ratio of GEARO/GEARI was greater than the highest allowable input frequency, 2MHz. This error breaks program execution and disables the BDS.

如是199#错误, 则过, 如不是, 则将错误码放入D65AH中, 然后看40.6H: 1过, 0则改为1。接下来把错误号转成ASCII码

Form error message and save it in 0E989H. According to some conditions the message may vary in parts

LFF35: Count lines

Entry of the error's title, such as "POWER BUS" Append this title

4653H: 0D 0A CR LF

FF34

